Robotina d.o.o.
OIC Hrpelje 38
SI-6240 Kozina
Slovenia

1. Troubleshooting

ERROR	POSSIBLE CAUSES	SOLUTION
CP positive/negative voltage	The voltage on the CP connector is out of permitted range	Check the charging cable and connector and reconnect the electric vehicle
	CPU	Intel Cherrytrail Z8350, 1.92Ghz quad core
	RAM	2 GB
	Storage	32 GB
	Operation System	Windows 10 Home + myHIQ
Communication	LAN	RJ45
	WiFi	802.11b/g/n
Power	Adapter	5V 3 A
	Battery	Optional